



New cast iron rainwater goods to be provided



Rainwater outlet—to be increased in size



Nave roof looking West



3 courses of slates stripped from South side of Nave roof and West side of South Trancept roof prior to gutter repairs

ST. MARY'S CHURCH, GRASSENDALE

ANTHONY GRIMSHAW ASSOCIATES LLP

architects designers + conservation consultants

6 BRIDGEMAN TERRACE WIGAN WNI ISX

T: 01942 245777 / E: aga@anthonygrimshawassociates.co.uk

Progress Photographs taken
30th October 2017

55002/A



Vestry roof at East end (no work done yet)



South Trancept roof



Nave roof

ST. MARY'S CHURCH, GRASSEDALE

Progress Photographs taken
30th October 2017

55002/B